

Installation Information


Requires EFJohnson Interface Cable Assembly (R5975357738)

Radio Interface for plugging into EF Johnson 25-Pin Accessory Port Connector F on the R5976367738 Interface cable

Cabin Speaker is connected to Connector B pins 1 & 2 of the R5975357738 Interface Cable

DO NOT USE WITH 597-5357-746-01 Cable.

RCB-xxJT Cable



Not to scale

Rear View

VM600 & VM900 Radio and R5975357738

