


Installation Information

Radio Interface for Hand Microphone Jack


NOTE: Radio Interface Requires Optional Kenwood Accessory Package (KAP-2) Which Includes Option Cable E37-1160-05 & Connector E59-0419-05 For Receive Audio Output.

Other Notes: KMC-35/36 hand microphones require "hot microphone" modification. See Kenwood service manual for details. Also, Not for use with TK-7160 and TK-7162 radios

MACB-KV Cable




Rear View Radio



(KAP-2) Which Includes Option Cable E37-1160-05 & Connector E59-0419-05 For Receive Audio Output

(KAP-2) E59-0419-05 Connector Rear View



Front View Radio

